

Volume VII-2, 1975

Some Notes on Architecture, Interiors, and Gardens in Quebec, 1831 ♦ The Case for Commemoration of Historic Landscapes and Gardens ♦ Metal Ceilings in the U.S. ♦ A Choice Assortment of Paper Hangings for Sale by the Subscribers ♦ Gardens of Shelburne, Nova Scotia, 1785-1820 ♦ Some Personal Observations on the Use of Paint in Early Ontario ♦ An Act for the Preservation of Apple Trees in the Parish of Montreal ♦ The Peter Wentz House: 18th Century Sponge Painting in Pennsylvania

Volume X-1, 1978

The Incidence of False Windows in Two Early Newfoundland Lighthouses ♦ Warren H. Manning's Drawings ♦ Training the Restoration Technologist ♦ A Unique Barracks Building at Niagara-on-the-Lake, Ontario ♦ Roman Stone and Other Decorative Artificial Stones ♦ The Site Arrangements of Rural Farmsteads ♦ A Masonry Deterioration Case Study: Holy Trinity Anglican Church, Hawkesbury, Ontario ♦ A Short Note on an Early Sash Window Found at East Hampton, Long Island

Volume XII-1, 1980

The Move and Restoration of the Hapgood Wool Carding Mill: A Case History from the 1960's ♦ Preservation Law, Building Codes and Assorted Prognostications ♦ Structural Reinforcement of Historic Wooden Temples in Japan ♦ Executed in Neatness of Pattern and Elegance of Colors: Reproduction Fabrics and Wallpapers

Volume XII-4, 1980

The Anatomy of a Late Nineteenth Century Padlock from Fort Charlotte, Grand Portage National Monument, Minnesota ♦ The Old Post Office and Federal Building in Dayton, Ohio: A Case History of

Restoration and Adaptive Use ♦ Demonstrating the Use of Log House Building Tools at New Windsor Cantonment ♦ A Brand-New 150 Year Old Drawing Frame ♦ Research and Storage: New Facilities for the Smithsonian Institution ♦ Inventing the I-Beam: Richard Turner, Cooper and Hewitt, and Others ♦ The Molded Brick Cornice in the Valley of Virginia

Volume XIII-1, 1981

Building Automation System at Iolani Palace, Honolulu, Hawaii ♦ Highlights in Pre-Confederation Quebec and Ontario as Seen through Travel Literature from 1762 to 1860 ♦ An Architectural Example of Oxide Jacking ♦ A Selected Annotated Bibliography for the Study of Newfoundland Vertical Log Structures

Volume XIII-4, 1981

In Delorme's Manner... ♦ An Early Victorian Passive Solar System: Eleutherian Mills ♦ Bargeboard Details in the Western Reserve of Ohio: 1830 – 1860 ♦ Central Pennsylvania Farmhouse Interiors: 1810 – 1850 ♦ Substitute Materials for Deteriorated Metal Building Components: The Rehabilitation of a Country Courthouse in Southern Georgia ♦ A Preliminary Study of 'English' Roofs in Colonial America

Volume XVI-3/4, 1984

A Study of Historic Paint Colors and the Effects of Environmental Exposures on Their Colors and Their Pigments ♦ Removal of Interior Coatings at the Statue of Liberty ♦ Preserving Historic Electric Lighting and Wiring at the Frederick Law Olmstead National Historic Site ♦ Plant Life at Historic Properties ♦ A Diagnostic Study and Treatment Evaluation for the Cleaning of Perry's Victory and International Peace Monument ♦ Photomicrography and the Stanton House Restoration ♦ Assessing the Effects of Vibrations on Historic Buildings ♦ Security

Panels for the Foster-Armstrong House

Volume XVIII-3, 1986

The Statue of Liberty, Systems within a Structure of Metal ♦ Preservation Maintenance in the Southwest ♦ Restoration of Electrical Systems in the James J. Hill House ♦ Preserving Historic Corridors in Open Office Plans ♦ Radiographic Inspection of Plank House Construction ♦ Protection of Historic Buildings during Construction ♦ The Rehabilitation of Bethesda Terrace ♦ Historic Preservation Maintenance in the Netherlands

Volume XIX-1, 1987

Maritime

Preservation

Lifting Lines from the Schooner Wawona ♦ Historic Structure Report: Wapama ♦ The Role of Maritime Surveys in Maritime Preservation ♦ The Role of Historical Research in Documenting Historic Vessels ♦ Fighting Rust ♦ Maritime Preservation Training Programs ♦ The National Register of Historic Places and Maritime Preservation ♦ Suggested Standards for the Maintenance of Historic Vessels ♦ Why Do We Save Ships? ♦ Interpreting Historic Vessels ♦ Preserving the Warships of World War II: Battleship Cove as a Case History ♦ Preservation at Pearl Harbor ♦ Developing a National Cultural Policy for Maritime Preservation ♦ Preserving Historic Vessels: A Long View of History ♦ Suggested Standards for Replica and Reproduction Vessels ♦ The Application of Preservation Technology to Historic Ships

Volume XIX-2, 1987

Letters on Landscape ♦ Museum Collection Storage Number 1: Museum Collection Storage in an Historic Building Using a Prefabricated Structure ♦ Heating and Cooling at the Robie House ♦ The Cape Hatteras Lighthouse: Diagnostics and Preservation ♦

Detecting Water Leaks in Slate and Clay-Tile Roofs ♦ Photo Drawings ♦ Slate Roofing

Volume XIX-3, 1987

Mortars for Tropical Archaeological Sites ♦ Windows: Number 10, Temporary Window Vents in Unoccupied Buildings ♦ Architectural Cast Iron: Design and Restoration ♦ Structural Upgrading of the Great Hall Ceiling, International House, University of California, Berkeley ♦ The Oregon Pony ♦ Turn-of-the-Century Floor Construction ♦ Managing Change in Vernacular Settings ♦ Stone Conservation and Consolidation: Salzburg's Franziskaner-kirche ♦ Recreating Historic Tile: The California State Capitol

Volume XX-2, 1988 Seismic Safety and Rehabilitation

Seismic Isolation Retrofitting ♦ Lessons on Bidding and Construction Management, Salt Lake City and County Building ♦ Seismic Retrofit of the Campton Place Hotel ♦ An Economic Perspective, Seismic Codes in Pioneer Square ♦ Rehabilitation of the Kaiser Convention Center ♦ Evaluating Buildings in Seismic Zones ♦ Seismic Rehabilitation of the Parra Adobe

Volume XX-4, 1988

Jacking Techniques for Log Buildings ♦ Making Mud Plaster ♦ Training in Crafts, Alberta's In-House Crew ♦ Stabilizing Ruins, Coal Mining Ruins at Leitch Collieries ♦ In-Situ Treatment of Paints, A Ukranian Catholic Church ♦ Analysis of a Ukranian Thatched Barn

Volume XXII-3, 1990 Adobe

Stabilization of Fort Selden's Ruins ♦ Spanish Colonial Polychrome Statuary: Replicating the Lions of San Xavier del Bac ♦ Celebrating the Quincentennial ♦ 'We've Got It, Tom' The Search for the First

Church of Abo ♦ Spanish Missions ♦ A Sixteenth Century Whaling Port ♦ Rebuilding Acoma Sky City ♦ Establishing an Underwater Archaeological reserve in the Florida Keys: A Case Study ♦ The Fort Selden Adobe Test Wall Project ♦ A Sixteenth Century Basque Whaling Port

Volume XXIII-2, 1991 The Recent Past

Detergents and Hypochlorites for the Cleaning of Travertine ♦ Neon Signs: Their Origin, Use, and Maintenance ♦ With Heritage So Shiny: America's First All-Aluminum House ♦ What Ever Happened to Lustron Homes? ♦ Preserving What's New ♦ The Significance of the Recent Past ♦ Investigative Technique for Water Penetration

Volume XXIII-3, 1991

Conservation Treatment of a Monumental Northwest Coast Wooden Sculpture ♦ Restoration of the South Wing at Hampton Court Palace ♦ Stabilization and Repair of a Historic Terra Cotta Cornice ♦ Diagnosis of Salt Damage at a Smokehouse in Colonial Williamsburg ♦ Tuck Pointing History and Confusion ♦ Immediate and Remote Techniques for Monitoring Humidity

Volume XXIII-4, 1991

Degradation of Monumental Bronzes ♦ Acidic Deposition and Marble Monuments at Gettysburg National Military Park ♦ A Twelve-Year Study of Precipitation Chemistry in Philadelphia ♦ Dry Deposition to Structures: Configuration Considerations ♦ Metal Corrosion, Wetness, and Deposition at the Exterior of a Building in Montreal ♦ Weathering of Crystalline Marble at the Field Museum of Natural History, Chicago ♦ Monitoring Urban Precipitation Chemistry in the Ville de Montreal ♦ Uniting Forces for Promotion of Cultural Heritage:

Interdisciplinary Cooperation Based in Goteburg ♦ Influence of Microclimate on the Deterioration of Historic Marble Buildings ♦ Weathering of Treated and Untreated Limestones in Atmospheric Exposures ♦ Acid Rain and Air Pollution vs. the Buildings and Outdoor Sculptures of Montreal

Volume XXIV-1/2, 1992

Severe Soil Deformations, Leveling, and Protection at the Metropolitan Cathedral in Mexico City ♦ Rebuilding the Historic Philippi Covered Bridge in West Virginia ♦ Understanding Regional Painting Traditions: The New Orleans Exterior Finishes Study ♦ Using Computer Processed Imagery to Facilitate Design Decision Making on Main Street ♦ Getting the Wet Out: Cleanup and Stabilization after a Fire ♦ Restoration of the Abbey Murals at the Pennsylvania State Capitol ♦ The Pompallier Project: Restoring a French Colonial Structure in New Zealand ♦ Historic Preservation and Hazardous Waste: A Legacy of the Industrial Past

Volume XXV-3/4, 1994

The Smeaton Project: Factors Affecting the Properties of Lime-Based Mortars ♦ The First Reversible Rim Lock and Some Contemporaries ♦ Evaporative Polystyrene Metal Casting Technology: Current Technique and Potential Application ♦ A Tribute to Lee H. Nelson ♦ Inventing the I-Beam, Part II: William Borrow at Trenton and John Griffen of Phoenixville ♦ Mechanic Geniuses and Duckies, A Revision of New England's Cut Nail Chronology before 1820 ♦ An Actual Mortar Analysis ♦ A Source of Confusion about Mortar Formulas ♦ Practical Aspects of Using Walnut Shells for Cleaning Outdoor Sculpture ♦ A Primer on Conservation Assessments and Emergency Stabilization for Historic Farm Buildings

**Volume XXVI-1,
1994 Computer
Technology**

Experiences in Rapid, Economical Surveys of Monuments at the Escuela de Estudios Arabes ♦ Digital Photogrammetry for Heritage Recording ♦ Smart Graphics: An Approach for Automated Expert Evaluation of Historic Structures ♦ Condition Assessment Using Computer Models ♦ Heritage Conservation through Computer Visualization ♦ Computers in Conservation: Toronto, Quebec City, and Afterward ♦ A Site Information System (SIS): CADD/Database Integration for Field Use ♦ Computer-Aided Recording: Proper Documentation for New Technology ♦ CAD and Its Emerging Role in Historic Conservation ♦ Desktop Digital Recording and Management Tools: From Ideas to End Products ♦ 3-D Models in the Service of the Past: Geomatics in Archaeology ♦ Photogrammetric Heritage Recording: Standard and Emergency Approaches

Volume XXVI-2/3, 1995

Bird Deterrence Technology for Historic Buildings ♦ Structural Evaluation of Historic Masonry Buildings ♦ Restoration of a Crossing Pinnacle at Washington National Cathedral ♦ Tiles and Pavers: Diagnostic Test Methods ♦ Chemical Stabilization of Adobe in the Restoration of the Montano Store ♦ Water-Repellent Treatments for Building Stones: A Practical Overview ♦ Transitional Timber Framing in Vermont, 1780-1850 ♦ Aqueous Acrylic/Epoxy Consolidants ♦ The Restoration of Stained Glass Windows at Memorial Hall, Harvard University: A Case Study

Volume XXVI-4, 1995

Symposium on Preservation Treatments for Historic Masonry ♦ Chemical Treatments for Masonry ♦ Acrylic Polymers for the

Conservation of Stone ♦ Factors Affecting the Selection of Water-Repellent Treatments ♦ The Use of Epoxy Resins for the Stabilization of Deteriorated Masonry ♦ Laboratory Tests and Evaluation of Proposed Masonry Treatments ♦ Guidelines for Consolidants ♦ Application Procedures for Masonry Treatments ♦ Lime Treatments: Lime Watering and Shelter coating for Friable Historic Masonry ♦ Consolidants, Coatings, and Water-Repellent Treatments for Historic Masonry

Volume XXVII-1/2, 1996

The Bollman Bridge at Savage, Maryland: Restoring America's Quintessential Metal Truss ♦ In a Tropical Marine Climate: Conservation Management of Historic Metals ♦ The Brickwork at Poplar Forest: Mr. Jefferson Builds His Dream Home ♦ The Education of Historical Architects and a Second Look at the NPS's Skills Development Plan ♦ Early Wooden Truss Connections vs. Wood Shrinkage: From Mortise-and-Tenon Joints to Bolted Connection ♦ Lee Nelson's Carpenter's Price and Rule Books ♦ Tributes to Lee H. Nelson ♦ Mechanic Geniuses and Duckies Redux: Nail Makers and Their APT Collectors' Sale Machines ♦ Architectural Fragments and APT: A Lee Nelson Legacy ♦ Applications of Non-Destructive Evaluation Techniques in Historic Buildings ♦ The Interaction of Timber and Brick Masonry in the Kathmandu Valley

**Volume XXVII-3, 1996
Museums and Historic
Buildings**

The New Orleans Charter: Forging a Strategy to Preserve Historic Structures and Artifacts ♦ The Process of Compromise: A Team Approach to Conservation Environments ♦ Alternatives to Modern Air-Conditioning Systems: Using Natural Ventilation and Other Techniques ♦ Humidity and Moisture in Historic Buildings: The Origins of Building and Object Conservation ♦ Diagnosis and

Suggested Measures for Moisture Control in a Historic Adobe House Museum ♦ What Made Lucy Rot? ♦ Quantified Risk Reduction in the Humidity Dilemma ♦ The Cabildo in New Orleans: Planning Museum Exhibitions in a Historic Building ♦ Museums in Historic Buildings ♦ Housing Museums in Historic Buildings: A Wise Solution in the Long Term?

Volume XXVII-4, 1996

An Introduction to Water Mist Fire-Suppression Technology ♦ Street Trees in Historic Downtowns: A Case Study of Danville, Kentucky ♦ Masonry in Retrospect: Mortar-Strength Experiments Conducted in France in 1834 ♦ Bond Capacities of Mortars for Historic Structures ♦ Restoration of the Kreuzberg Monument: A Memorial to Prussian Soldiers ♦ A Multi-Media System for Organizing Architectural Documentation of Historic Buildings ♦ Hard Hat House Tours? Interpreting Restoration Projects ♦ Rodney Takes a Heck of a Ride: A 12-Step Recovery Program for a Statue ♦ Borate Wood Protection Compounds

Volume XXVIII-1, 1997

Historic Structure

Reports

Evolution of Historic Structure Reports at the U.S. National Park Service ♦ The West Block of Parliament, Ottawa: An HSR Case Study ♦ Historic Structure Reports in France: A History of Guidelines and a Case Study ♦ Preserving New England's Rural Landscapes: The Property Plan for Eastman Hill, Lovell, Maine ♦ Watching the Evidence: An HSR to Guide the Preservation of George Washington's Mount Vernon ♦ Louisiana HABS Online: The Whitney Plantation Prototype ♦ The Conservation Analysis: An Australian Perspective ♦ A Historic Structure/Cultural Landscape Report: South Manitou Island Light Station ♦ A Significance-Driven Approach to the Development of the Historic Structure Report ♦

Reading Buildings instead of Books:
Historic Structure Reports as
Learning Tools

Volume XXVIII-2/3, 1997

Historic Linoleum: Analysis,
Cleaning Systems,
Recommendations for
Preservation ♦ Masonite: Versatile
Modern Material for Baths,
Basements, Bus Stations, and
Beyond ♦ Reversible Latch Rim
Locks: Late Nineteenth-Century
Popular Hardware ♦ Computer-
Assisted Optical Stereology in
Historic Preservation: Tabby, a
Case Study ♦ Making Magic:
'Suspended Columns' at
Princeton's Whig and Clio Halls ♦
Homosote: The 'Greatest Advance
in 300 Years of Building
Construction' ♦ The Bayt al-Razzaz
Palace: Developing an Existing
Conditions Report ♦ Understanding
Historic Tabby Structures: Their
History, Preservation, and Repair ♦
Frank Lloyd Wright's Banff Pavilion:
Critical Inquiry and Virtual
Reconstruction ♦ Beaver Board
and Upson Board: History and
Conservation of Early Wallboard ♦
The Nightingale-Brown House:
Eighteenth-Century Ornament
Meets Twentieth-Century Scholar

**Volume XXVIII-4,
1997 Modern
Heritage**

Conserving the Built Heritage of
the Modern Era: Recent
Developments and Ongoing
Challenges ♦ A Material Evaluation
of the Gropius House: Planning to
Preserve a Modern Masterpiece ♦
Repair of Mies van der Rohe's
Promontory: A Multiphased
Approach to Façade Restoration ♦
Concrete Repairs: Electrochemical
Preservation Techniques ♦ The
Pristine Plane: Plaza Paving
Technology in Modern
Architecture ♦ Authenticity is More
Than Skin Deep: Britain's Postwar
Concrete Architecture ♦ Moisture
Control in the Modern Building
Envelope: History of the Vapor
Barrier in the U. S., 1923-52

Volume XXIX-1, 1998

Non-Destructive Evaluation of a
Historic Wrought-Iron Truss Bridge in
New Braunfels, Texas ♦
Metallurgical Assessment of
Historic Wrought Iron: U. S. Custom
House, Wheeling, West Virginia ♦
Defying Gravity: The Resurrection
of Architectural Terra-Cotta
Fragments ♦ Energy Simulation of
Historic Buildings: The St. Louis
Catholic Church, Castroville, Texas
♦ Ethyl Silicate as a Treatment for
Marble: Conservation of St. John's
Hall, Fordham University ♦ Structural
Glued Laminated Timber: History
and Early Development in the
United States ♦ Reign of Terra
Cotta in the United States:
Enduring in an Inhospitable
Environment, 1930-1968

Volume XXIX-2, 1998

Three-Dimensional Modeling of
Erosion to Historic Adobe Wall
Ruins at Fort Davis, Texas ♦ Frost
Durability Testing of Stone Masonry
Mortars: Restoring the Canadian
Parliament Buildings ♦ In Search of
Durable Repair Mortar for Historic
Masonry in Northern Climates: A
Prologue ♦ Mortar Study of
Mechanical Properties for the
Repointing of the Canadian
Parliament Buildings ♦ Emergence
of Cast-Iron Architecture in the
United States: Defining the Role of
James Bogardus ♦ Surrealist Vision
and Cold Reality: Restoration of
Marc Chagall's 'Les Quatre
Saisons' ♦ Inventing the
Adirondack Log Villa: From
Woodsman's Cabin to Rustic
Lodge ♦ Assessing Wood Members
in the USS Constitution Using Non-
Destructive Evaluation Methods

**Volume XXIX-3/4,
1998 Thirtieth**

Anniversary
Three Decades of Interdisciplinary
Preservation Technology: APT
Celebrates Its Thirtieth Anniversary
♦ Collections in Historic Structures:
A Review of Professional Progress
Since the New Orleans Charter ♦
Training the Trades for Masonry

Conservation: Integrating
Conservation Ideals and
Traditional Skills ♦ Heritage Tourism
in the USA: Grassroots Efforts to
Combine Preservation and Tourism
♦ HABS/HAER at the Millennium:
Advancing Architectural and
Engineering Documentation ♦ Time
for Change: An Overview of
Building-Materials Research for
Conservation of Historic Structures
♦ Current State of Historic
Preservation Engineering: One
Engineer's Point of View ♦
Promoting the Preservation of
Historic Buildings: Historic
Preservation Policy in the United
States ♦ Policy Issues and Their
Impact on Practice: Heritage
Conservation in Canada ♦ Historic
Landscape Conservation in North
America: Roaming the Field Over
the Past Thirty Years ♦ Cultural
Heritage Tourism Planning and
Development: Defining the Field
and Its Challenges ♦ International
Trends in Historic Preservation: From
Ancient Monuments to Living
Cultures ♦ Historic Preservation
Education: Academic Preparation
for Practice

**Volume XXX-1, 1999
Gardens and
Landscapes**

Recovering from a Devastating
Tornado at Andrew Jackson's
Hermitage: A Case Study ♦ Case
Study in Ecosystems and
Preservation: Lessons Learned from
New York's Central Park ♦
Vegetation Management in Large
Cultural Landscapes: Techniques
for Preserving Historic Fields and
Vistas ♦ Trees Have a Heartbeat,
Too: Micro-Drilling Devices for
Landscape Conservation ♦
Restoring Landscape Character at
Fairsted, the Frederick Law
Olmstead National Historic Site ♦
Family Tree of Historic Landscape
Preservation: Encouraging
Dialogues about Shared
Relationships ♦ Documenting
Garden and Landscape History:
The Catalogue of Landscape
Records in the U.S. ♦ Messages
Along the Roadside Landscape: A
Vanishing Art Remembered with

Nostalgia ♦ Reconciling Aesthetic Value and Social Value: Dilemmas of Interpretation and Application ♦ Leimert's Park Plaza: Cultural Landscape Rehabilitation in Community Revitalization ♦ Some Basic Cultural Landscape Preservation Resources: A Review of Available Information

Volume XXX-2/3, 1999

Hunterdon County's Stone-Arch Bridges: History, Technology, and Preservation ♦ The Architecture of Mud: Construction and Repair Technology in the Hadhramaut Region of Yemen ♦ Restoring the Minton Tile Ceiling, Bethesda Terrace Arcade, Central Park, New York City ♦ Discovering Dumbarton Oaks: Restoring a Masterwork for Modern Needs ♦ Digital Vector Data and Heritage Applications: Development, Usage, and Current Status ♦ A Prototypical Historic Fire-Risk Index to Evaluate Fire Safety in Historic Buildings ♦ Heritage Stewardship and the Amateur Tradition ♦ Designing a Test Blasting Program for an Underground Building on Parliament Hill ♦ Re-Lighting a Historic Church Interior: Challenges at Cornell University's Sage Chapel ♦ Comfortable, Durable, and Decorative: Linoleum's Rise and Fall from Grace.

Volume XXX-4, 1999

Guastavino Company

Rafael Guastavino's Construction Business in the United States: Beginnings and Development ♦ Restoration of the Queensboro Bridge Guastavino Vaults: A Case Study ♦ Restoration of the Oyster Bar at New York's Grand Central Terminal: A Case Study ♦ The Guastavino System in Context: History and Dissemination of a Revolutionary Vaulting Method ♦ Preserving Historic Guastavino Tile, Ceilings, Domes, and Vaults: An Overview ♦ The Unseen World of Guastavino Acoustical Tile Construction: History, Development, Production ♦

Seismic Considerations for Guastavino Ceiling, Vault, and Dome Construction ♦ Structural Repairs to Fire-Damaged Guastavino Tile Vaults at Grand Central Terminal's Oyster Bar .

Volume XXXI-1, 2000 Museum Lighting

Lighting a Great House and a Museum: Waddeson Manor, a Case Study ♦ An Overview of Light and Lighting in Historic Structures That House Collections ♦ APT/AIC Guidelines for Light and Lighting in Historic Buildings That House Collections ♦ APT/AIC New Orleans Charter for the Joint Preservation of Historic Structures and Artifacts ♦ Chasing Shadows: Exploring the Meaning of Light in English Heritage Houses ♦ Controlling Daylight in Historic Structures: A Focus on Interior Methods ♦ Lighting the Way: A Conservator's Approach to Electrifying Brass Chandeliers ♦ 'Luminous and Splendid': Lighting Colonial Williamsburg Interiors by Candlelight ♦ Lighting Jefferson's Monticello: Considering the Past, Present, and Future ♦ A Look at Nineteenth-Century Lighting: Lighting Devices from the Merchant's House Museum

Volume XXXI-2/3, 2000

Fire-Safety Retrofitting: Innovative Solutions for Ornamental Building Interiors ♦ Control of Formosan Subterranean Termites in Perseverance Hall in New Orleans, Louisiana ♦ Relocating the Cape Hatteras Lighthouse in Buxton, North Carolina ♦ Environmental Monitoring and Conservation Study of Drayton Hall in Charleston, South Carolina ♦ Ambiguity in Building Investigation: A Study of Sampling and Decision-Making with Field Data ♦ The Village of Chazhashi: Georgian Svannish Vernacular Architecture ♦ And It Never Needs Painting: The Development of Residential Aluminum Siding ♦ The Rise and Fall of West Coast Modernism in

Greater Vancouver, British Columbia ♦ When the Imitation Becomes Real: Attitudes toward Asphalt and Asbestos-Cement Roofing and Siding

Volume XXXI-4, 2000 Landscapes and Gardens

Civilian Conservation Corps Initiative: Cultural Resources in Massachusetts Forests and Parks ♦ Associative Values: Exploring Nonmaterial Qualities in Cultural Landscapes ♦ Drafting the Vimy Charter for Conservation of Battlefield Terrain ♦ Commemorative Integrity and Cultural Landscapes: Two National Historic Sites in British Columbia ♦ Preserving Battlefield Terrain: Technologies for Earthworks Management ♦ Endangered Landscapes: Residential Alley Transformations ♦ The Family Tree: Looking at the Roots of Historic Landscape Preservation

Volume XXXII-1, 2001 Curtain Walls

This Stone Systems: Conflicts between Reality and Expectations ♦ Authenticity Considerations for Curtain-Wall Buildings: Seminar Summary ♦ Conflicts and Challenges in Preserving Curtain Walls ♦ Focus on Glass ♦ Guide to the Use of New ASTM Standards for Sealants ♦ Timber Decay in Buildings: The Conservation Approach to Treatment ♦ Thin-Stone Veneer Building Facades: Evolution and Preservation ♦ Glass and Metal Curtain-Wall Fundamentals ♦ The Origins of the Modern Curtain Wall

Volume XXXII-2/3, 2001

Promoting the 'Unit Idea': Manufactured Kitchen Cabinets (1900-1950) ♦ The Renovation of Baker House at MIT: Modernism, Materiality, and the Factor of Intent in Preservation ♦ Centre Street Bridge Lions: Rehabilitation and Replication of Historic Concrete Sculpture ♦ The Mormon

Cultural Landscape at Stirling Agricultural Village, Alberta ♦ Floor Vibration: A Possible Assessment Method for Historic Buildings ♦ Working for a Genius: My Time with Albert Kahn ♦ Some Perspectives on Falun Red Paint and the Red Cottage, Sweden's 'National Building' ♦ The Philosophy of Rose Greely, Landscape Architect

Volume XXXII-4, 2001 Terra Cotta

O. W. Ketchum Terra Cotta: Reflections on an Industry in Chaos after World War II ♦ Survey of Terra-Cotta Facades at Alwyn Court, a Case Study ♦ Terra Cotta Tile Mosaics at Sea View Hospital: Endangered Glazed Ceramics on Staten Island ♦ Anchoring Systems for Architectural Terra Cotta in Curtain-Wall Construction ♦ Fallingwater Part 1: Materials-Conservation Efforts at Frank Lloyd Wright's Masterpiece ♦ The Good, the Bad, and the Ugly: Twenty Years of Terra Cotta Repairs Reexamined ♦ The Evolution of Terra Cotta: 'Glazing New Trails'

Volume XXXIII-1, 2002 Architecture and Craft

Converging Disciplines during Structural and Environmental Upgrades: The Troxell-Steckel House ♦ Building Craftsmanship, Capacity, and Relationships: The Preservation Trades Network ♦ Convergence of Design and Craft: Planning the Restoration of an Eighteenth-Century Cloister ♦ Conservation of Historic Building-Trades Education: A Timber-Framer's View ♦ Selected Writings from the Journal of a Craftsman ♦ Restoration of the Concrete Roof of the Mercer Museum in Doylestown, Pennsylvania ♦ Mobile Preservation Construction Services: The Pennsylvania Historical and Museum Commission ♦ Passing on the Legacy: Vocational Education for the Preservation Trades ♦ Architecture and Craft: A New York City Government Perspective ♦ A Team Approach to Involving

the Trades at the Pennsylvania Historical and Museum Commission

Volume XXXIII-2/3, 2002

Color and Long-Term Color Retention in Composite Patching Systems for Stone and Masonry ♦ Timber Assessment at Quincy Mine Blacksmith Shop, Keweenaw National Historical Park ♦ Plastic Dreams: Weathering of Glass-Reinforced Plastic Facsimiles ♦ Assessing Past Conservation Treatments at George Washington's Mount Vernon ♦ Wallpaper Documentation and Reproduction at Adena: The Worthington Estate ♦ Survivors among the Ruins: Traditional Houses in Earthquakes in Turkey and India ♦ The Variable Performance of Ethyl Silicate: Consolidated Stone at Three National Parks ♦ Ancient Newari Water-Supply Systems in Nepal's Kathmandu Valley

Volume XXXIII-4, 2002

New Developments in Fluorinated Materials for Stone Preservation ♦ Coloring Historic Stucco: The Revival of a Past Technique in San Juan, Puerto Rico ♦ Using Electro-Osmotic Pulse Technology to Prevent Rising Damp and Moisture Intrusion ♦ The Princeton University High-Reach Project: A Creative Approach to Preservation Contracting ♦ Restoring and Modernizing the U.S. Treasury Building: An Overview and Three Case Studies ♦ Applying Infrared Thermography to Historic Wood-Framed Buildings in North America ♦ New Consolidants for Historic Plaster: Studies at the Knickerbocker Mansion in Upstate New York

Volume XXXIV-1, 2003

Why Lived-in Landscapes Matter to Nature Conservation ♦ Using Infrared Thermography to Detect Moisture in Historic Masonry: A Case Study in Indiana ♦ Restoration and Emergency

Stabilization at the Resurrection New Jerusalem Monastery in Russia ♦ Stereological Solutions to Monitoring Buildings: Case Studies of Sod and Tabby Structures ♦ Structural Triage of Historic Buildings: Combining Safety and Preservation Interests after Disasters ♦ Flash-Flood Impacts and Protection Measures in the Valley of the Kings, Luxor, Egypt ♦ Perestroika Conservation: The Effort to Save Abandoned Log Churches in Russia

Volume XXXIV-2/3, 2003

Conserving the Ruins of a Hellenistic Farmhouse in Crimea, Ukraine ♦ A pioneering Effort: The California State Historical Building Code ♦ A GIS Assessment of the Great Hall Ceiling at Drayton Hall, Charleston ♦ Survey Methodology for Preservation of Historical Burial Grounds and Cemeteries ♦ Detecting Subterranean Termite Activity with Infrared Thermography: A Case Study ♦ Methods for the Preservation of French Colonial Poteaux en Terre (Posts-in-Ground) Houses ♦ A Study of Seismic Protection Techniques for the Byzantine Churches in Macedonia ♦ Shaking Up Historic Buildings

Volume XXXIV-4, 2003

Rehabilitation Codes Come of Age: A Search for Alternate Approaches ♦ Considering Fire-Safety Improvements to Historic Buildings ♦ The New Jersey Rehabilitation Subcode and Historic Preservation ♦ Fire-Risk Indexing: A Systematic Approach to Building-Code "Equivalency" for Historic Buildings ♦ Main Street and Building Codes: The "Tin Ceiling" Challenge ♦ Automatic Fire Suppression for Historic Structures: Options and Applications ♦ Planning Projects to Prevent Damage during Construction: A Property Owner's Primer ♦ Conservation of Bridges

Volume XXXV-1, 2004

Guidance for Security Enhancements to Historic Buildings ♦ Tweed Courthouse: New Approach to Life-Safety Management in a Landmark Public Building ♦ Protective Design of Exterior Building Components in Twentieth-Century Historic Structure ♦ Repairing Blast Damage at the South Portico of the California State Capitol ♦ Perimeter Security Retrofitting for Historic Buildings ♦ The Federal Emergency Management Agency and Its Role in Historic Preservation ♦ Heavy Timber Framing in Late-Nineteenth-Century Commercial and Industrial Buildings

Volume XXXV-2/3, 2004

Restoration of Door Hardware at Monticello: Unlocking Some Mysteries ♦ Metallurgical Investigation of an Iron Cable Wire in a Gries-Gendell (Severson) Girder ♦ Bringing Back the Magic: Restoring Giuseppe Moretti's Vulcan in Birmingham, Alabama ♦ Historic Carpentry in Europe: Discoveries and Potential ♦ Replicating the John J. Earley Concrete Mix to Restore the Nashville Parthenon ♦ The Conservation of Heritage Submarines ♦ Acadia Style: Using Historic Precedents to Rehabilitate Hiking Trails ♦ Soldier Field Stadium: Corrosion Mitigation for Historic Concrete

Volume XXXV-4, 2004

The Value of Old Bridges ♦ From Craft to Science: American Timber Bridges ♦ Condition Assessment of Timber Using Resistance Drilling and Digital Radioscopy ♦ Saving Covered Bridges with Glass-Fiber-Reinforced Polymers ♦ Lateral Bracing in Covered Bridges and the Naturally Curved Knee ♦ Parallel Developments, Technology Transfer, and Scotland's Place in the International Dimension

Volume XXXVI-1, 2005

Preservation Engineering: The

Future ♦ Should Preservation Engineering Require Certification ♦ A Philosophy for Preservation Engineers ♦ GPS: A New Tool for Structural Displacement Measurements ♦ Cathodic Protection of Iron and Steel in Heritage Buildings in the United Kingdom ♦ Locating Faults in Wall Paintings at the U.S. Capitol by Shaker-Based Laser Vibrometry ♦ Evaluation of Built-Up Timber Trusses in Late- Nineteenth- and Early- Twentieth-Century Buildings ♦ Nondestructive Analysis of and Strengthening Design for a Historic Church Tower in Kentucky ♦ Monitoring the Long-Term Performance of the Peace Tower in Ottawa

Volume XXXVI-2/3, 2005

Case Studies in Diagnosis and Repair of Historic Thin-Shell Concrete Structures ♦ A Mausoleum on Shaky Ground ♦ Delaminations in Concrete: A Comparison of Two Common Nondestructive Testing Methods ♦ Wood Assessment and Repair of Gustav Stickley's Log House at Craftsman Farms, New Jersey ♦ Bridging the Gap ♦ "Let US Raise a Standard..." ♦ Digital Reproduction of Historic Wallpaper at the Paul Laurence Dunbar House in Ohio ♦ Comments in Memory of APT College of Fellows Members

Volume XXXVII-1, 2006

Prefabrication in the Gold-Rush Era: California, Australia, and the Pacific ♦ Cement and Concrete, Creativity and Community, and Charles E. Peterson ♦ Structural Systems of the Bollman Truss Bridge at Savage, Maryland ♦ Discovery through Documentation: The Investigation of Historic and Cultural Resources ♦ Dry-Press Brick: A Nineteenth-Century Innovation in Building Technology ♦ Preservation Technology Comes of Age in North America: Part 1

Volume XXXVII-2/3, 2006

Fallingwater Part 2: Materials-

Conservation Efforts at Frank Lloyd Wright's Masterpiece ♦ Conservation in Tilting, Newfoundland: Rugged Landscapes, Strong People, Fragile Architecture ♦ Forensic Investigation Methodology For Structures Experiencing Settlement ♦ A Practical Technique for Injection of Consolidants behind Wall and Ceiling ♦ The Development and Use of a Tablet PC Annotation System for Conditions Surveys ♦ Performance of Injection Adhesives for the Great Hall Ceiling at Drayton Hall, Charleston ♦ Preservation Technology Comes of Age in North America: Part 2

Volume XXXVII-4, 2006

Design Excellence and Historic Preservation ♦ Gathering New Ideas for the Practice of Preservation through International Discussion ♦ Respecting Significance and Keeping Integrity: Approaches to Rehabilitation ♦ Responding to Context: Changing Perspectives on Appropriate Change in Historic Settings ♦ Designing for Building Performance: The Management of Change ♦ Encouraging Excellence while Maintaining Standards: An Ongoing Discussion ♦ Standards for the Conservation of Historic Places in Canada ♦ The Security of the Interior's Standards for Rehabilitation ♦ The International Charter for the Conservation and Restoration of Monuments and Sites (Venice Charter) ♦ The Burra Charter: The Australia ICOMOS Charter for the Conservation of Places of Cultural Significance ♦ Patrimony and Pragmatism: Design Excellence and Historic Preservation Symposium Speaker Biographies ♦ Patrimony and Pragmatism: Design Excellence Preservation

Volume XXXVIII-1, 2007

The Fallacies of Intent: "Finishing" Frank Lloyd Wright's Guggenheim Museum ♦ Paint, Caen Stone, and Acoustical Plaster at the Public

Library in Mobile, Alabama ♦ The Effect of Pressed-Metal Ceilings on Floor Stiffness ♦ Practice Points 2 Follows Page 30, The Metropolitan Floor: Modern Analysis of an Archaic Structure ♦ Structural Modeling for Lateral Stiffness in Historic Truss Bridges ♦ Earthen and Loam Building Technology in Austria

Volume XXXVIII-2/3, 2007

Testing Alternatives to Conventional Air Conditioning in Coastal Georgia ♦ Damage to Buildings from Future Climate and Pollution ♦ Durability of Traditional and Modified Limewashes ♦ Fort Mackinac Restoration ♦ Practice Points Number 3 Follows Page 36, Basics of Wood Inspection: Considerations for Historic Preservation ♦ Holistic Approach to the Rehabilitation of Foundouks in Morocco ♦ New Life for the Chancel Window at Bigelow Chapel, Mount Auburn Cemetery, Massachusetts ♦ Case Study of a Church Bell Tower: Undoing Previous Inadequate Repairs ♦ Lee Nelson Award Winner 2006: Water in Buildings

Volume XXXVIII-4, 2007

Is Preservation Technology Neutral ♦ Sound: Exploring a Character – Defining Feature of Historic Places ♦ The Development of Finite-Element Models and the Horizontal Thrust of Guastavino Domes ♦ Practice Points 4 Follows Page 30, Through a Lens Clearly ♦ Effects of Vitrification on Traditional Terrazzo ♦ The Restoration of the Fifth Avenue Facades of the Metropolitan Museum of Art

Volume XXXIX-1, 2008

A Flood of Light: H.H. Richardson's Great Western Staircase at the New York State Capitol ♦ Identification of 1850s Brown Zinc Paint Made with Franklinite and Zincite at the U.S. Capitol ♦ Mortar Analysis Part 1: Mortar-Making Materials ♦ Fabricating and Installing Side-Lap roof Shingles in

Eastern Pennsylvania ♦ Rediscovering Sustainable Design through Preservation: Bauhaus Apartments in Tel Aviv

Volume XXXIX-2/3, 2008

An Introduction to Authenticity in Preservation ♦ Origins and Influence of the Nara Document on Authenticity ♦ From Warsaw to Mostar: The World Heritage Committee and Authenticity ♦ Considering the Authenticity of Cultural Landscapes ♦ World-Heritage Historic Urban Landscapes: Defining and Protecting Authenticity ♦ Practice Points Number 6 Follows Page 38, Architectural Finishes: Research and Analysis ♦ The Nara Grid ♦ Applying Authenticity to Cultural Landscapes ♦ Regional Authenticity: An Argument for Reconstruction in Oceania ♦ Authenticity in Aboriginal Cultural Landscapes

Volume XXXIX-4, 2008

The Legacy of French Colonialism ♦ Reproducing Historic Wallpapers at the Grand Opera House, Meridian, Mississippi ♦ High-Calcium Lime Mortar: The Effects of Traditional Preparation and Curing ♦ Appropriate Means to an Appropriate End: Industry, Modernism, and Preservation ♦ Using Natural Resources for Ventilation ♦ Grouting as a Strengthening Technique for Earthen Structures in Seismic Areas

Volume XL-1, 2009

Sustainable Heritage: Challenges and Strategies for the Twenty-First Century ♦ The Use of Lasers for Cleaning Large Architectural Structures ♦ Mortar Injection: A Case Study of the Villa Medici in Rome ♦ Blanketing the Home: The Use of Thermal Insulation in American Housing ♦ Analyzing Mortars and Stuccos at the College of Charleston: A Comprehensive Approach ♦ Abandoned in the Wilderness: Survival and Rescue at the

Adirondack Iron Works ♦ Condition Evaluation of Facades of Nineteenth-Century New York City Walk-Ups

Volume XL-2, 2009

A Grading Protocol for Structural Lumber and Timber in Historic Structures ♦ An Analysis of the Thermal Performance of Repaired and Replacement Windows ♦ Sustainable Solutions for Historic Buildings ♦ Practice Points Number 7 Follows Page 28, Mortar Analysis Part 2: Analytical Methods ♦ Did it Work? Post-Restoration Evaluation of Terra Cotta at Atlantic City Hall ♦ Conservation Treatments for Earthen Structures in the Western Himalayas of India ♦ Lee Nelson Award Winner 2008: Preservation of Modern Architecture

Volume XL-3/4, 2009

Introduction to the Fortieth-Anniversary Issue ♦ Towards a New Era of Cultural-Heritage Recording and Documentation ♦ Safety and Building Codes: The Recent Past and Future for Historic Structures ♦ Sustainable Design in Historic Buildings: Foundations and Future ♦ Preserving Engineering: Past, Present, and Future ♦ Climate Change and Landscape Preservation: A Twenty-First Century Conundrum ♦ Academic Preparation for Preservation Practice ♦ Making the Project Real: Changes in Delivery of Concept to Construction ♦ Update on Building-Materials Research ♦ Make No Small Plans: How Strategic Planning Shaped APT from 1995 to 2008 ♦ Dissemination of Knowledge through Publication ♦ APT Historical Supplement

Volume XLI-1, 2010

Coming of Age ♦ Saving Energy in Historic Buildings: Balancing Efficiency and Value ♦ Green Home-Rating Systems: A Preservation Perspective ♦ Sustainable Heritage Conservation: Pere Marquette Railroad Depot in Michigan ♦

Practice Points Number 8 Follows
Page 28, Using Dry Ice for Spray-
Paint Removal on Weathering
Steel ♦ Thermal Performance of
Traditional Windows and Low-Cost
Energy-Saving Retrofits ♦
Sustainability: The Case for Long-
Term Service Life and Built-In
Redundancy ♦ Teaching
Sustainability to Preservation
Students

Quantities are Limited.

Place your order today!